

(1)エレベータホール・非常口 1F



▲ 施工前



▲ 施工後

(2)正面入口 1F



▲ 施工前



▲ 施工後

(3)食堂



▲ 施工前



▲ 施工後

(4)廊下 2F



▲ 施工前



▲ 施工後

(5)廊下 3F



▲ 施工前



▲ 施工後

(6)廊下 4F



▲ 施工前



▲ 施工後

(7)廊下 5F



▲ 施工前



▲ 施工後

(8)廊下 6F



▲ 施工前




▲ 施工後

(9)廊下 7F



▲ 施工前



▲ 施工後

(10)廊下 8F



▲ 施工前



▲ 施工後

(11)廊下 9F



▲ 施工前



▲ 施工後

(12)建物裏側



▲ 施工前



▲ 施工後



● 事務所 (DVR・モニター設置位置)



▲ 施工前



▲ 施工後

